



Earthquake Insights Seminar: Unveiling Discoveries and Preparedness Strategies

Lessons Learned from the M7.8 Türkiye Earthquake of 6 February 2023

October 13, 2023





We would like to acknowledge that we reside on the unceded traditional territories of the $x^w m\theta k^w \acute{e}y\grave{e}m$ (Musqueam), $S_k w x_w \acute{u}7 mesh$ (Squamish), and $s\grave{e}lilw\acute{e}t\acute{a}l$ (Tseil-Waututh) Nations.

General Agenda

| TIME | TITLE |
|--------------------|---------------------------|
| 1:00 - 1:05 | Opening Remarks |
| 1:05 - 2:00 | Technical Session |
| 2:00 - 2:20 | Break |
| 2:20 - 3:20 | Technical Session |
| 3:20 - 3:40 | Break |
| 3:40 - 4:20 | Technical Session |
| 4:20 - 4:50 | Panel Discussion |
| 4:50 - 5:00 | Concluding Remarks |




Certificate of Attendance

Participants who are both registered and in attendance will receive a Certificate of Attendance for 3.5 Professional Development Hours (PDH) from UBC.

Please confirm and submit your details in order to receive your PDH certification.

engineering.ubc.ca/COA



Opening Remarks


Mr. Hüseyin Emrah Kurt, General Consul of Türkiye



1. Introduction

Tony T.Y. Yang, Ph.D., P.Eng., F.CAE, Professor, UBC
Alemdar Bayraktar, Visiting Professor, UBC





Dedicated to the lives lost during the 2023 Türkiye Earthquake & the effort to mitigate lives lost in future earthquakes.

Team:



Tony T.Y. Yang
Professor
UBC



Carlos Ventura
Professor
UBC



Alemdar Bayraktar
Visiting Professor
UBC



Svetlana Brzev
Adjunct Professor
UBC



Mehrtash Motamedi
Research Associate
UBC



Bishnu Pandey
Instructor
BCIT



Allison Chen
Practice Advisor
EGBC



Jeffrey Salmon
Structural Engineer
Ausenco Eng. Canada



Keshab Sharma
Geotechnical Engineer
BGC Engineering



Şerife Özata,
Architect
AEU, Kirsehir



Omar AlShawa
Research Associate
SUR



Veljko Kokovic
Assistant Professor
U of Belgrade



Acknowledgement:

UBC APSC

SEABC
program

certificate

CAE



THE UNIVERSITY OF BRITISH COLUMBIA

Engineering

Faculty of Applied Science



All local contacts in Türkiye:

Ali Gemci, Director of Urban Planning of Onikişubat Municipality; Ali Gül, Headman of Hacilar Village; Ali Osman Coşkun, Hüseyin Sünnetçioğlu, Abdulmutalip Barubay, Sedat Humartekin in BRY and GNR Altyapı Inc.; Alpay Atmaca, Engineer in Osmaniye State Hospital; Bülent Haksal, Director of Disaster Coordination of Gaziantep Municipality in Nurdağ; Eflahun Yıkıcı, Guard in Kartalkaya Dam in Pazarcık; Engin Özer, The deputy mayor of Antakya Municipality; Enver Kaya, Controller in the Kartalkaya Dam; Erdoğan Emrah Hatunoğlu, Director of Foreign Relations of Kahramanmaraş Municipality; Halil Satıcı, Manager of Social Affairs of Gaziantep Municipality in Nurdağ; Hasan Ay, District Director of National Education in Kırıkhan; H. Abdullah Dinç, Head of Industrial Vocational High School in Kırıkhan; İbrahim Hızıyolu, Director of Disaster Coordination of Gaziantep Municipality in İslahiye; Kemal Topçu, Head of 75. Yıl Kindergarten in Kırıkhan; M. Fatih Tosyalı, Mayor of İskenderun Municipality; Metin Çiftçi, Site Manager of the Tunnel and Bridge in Gölbaşı; Muharrem S. Bilgiç, Project Coordinator in Intek Inc. in İslahiye; Mürsel Koçer, Head of Osmaniye State Hospital; Rüstem Keleş, General Secretary of Kahramanmaraş Municipality; Sait Bayraktar, District Director of National Education in Hassa; Osman Tuğrul Adıgüzel, Head of Bahçe High School in Bahçe; Özgür İspir, Representative of Chamber of Civil Engineering in Elbistan; Uğur Pekmez, Pekmez Inc. in Kahramanmaraş; Uğur Yücel, Architect in Gölbaşı; Yusuf Dedeoğlu, Head of Hacilar Middle School in Hassa;



THE UNIVERSITY OF BRITISH COLUMBIA

Engineering

Why earthquakes?

- Earth was formed about 4.5 billion years ago.




Why earthquakes?



Why earthquakes?




Why earthquakes?




Past earthquakes:





Patterson Cylindrical Projection

Symbol drawing order: more deaths on top of fewer deaths; smaller magnitude earthquakes on top of larger magnitude earthquakes.



~850 km

Türkiye

Gaziantep

Adana

Mersin

Cyprus

Syria

Lebanon

Beirut

Damascus

Iraq

Baghdad

Khorramabad

Romania

Bucharest

Bulgaria

Plovdiv

Thessaloniki

Greece

Athens

Krasnodar

Sevastopol

Georgia


Tbilisi

Armenia

Azerbaijan

Baku

2023/2/20 – 2023/5/6: > 35,000 aftershocks (where > 500 with M4 & M5)





➤ 11 major cities centers were affected:


➤ 161 municipalities & 1,300 villages

➤ >100,000 km² affected (included Syria)

➤ >14 million people affected

➤ > 60,000 deaths (include Syria)

➤ >2.5 million buildings are affected by the earthquakes.



Hatay

Population: 1.6 million



Hatay







Kahramanmaraş:
Population: 1.1 million



Kahramanmaraş



Kahramanmaraş



Adıyaman
Population: 632,148



Adiyaman



Osmaniye
Population: 559,405



Osmaniye




Building information:

Total building inventory: 2.5 million


| Province | Building construction year (%) | | | |
|-------------------|--------------------------------|-----------|---------------|---------|
| | 1980 or before | 1981-2000 | 2001 or after | unknown |
| Adana | 13.0 | 34.8 | 38.7 | 13.5 |
| Adıyaman | 8.7 | 23.6 | 52.3 | 15.4 |
| Diyarbakır | 6.5 | 26.6 | 57.1 | 8.8 |
| Elazığ | 10.0 | 23.6 | 52.8 | 13.6 |
| Gaziantep | 6.6 | 25.9 | 51.6 | 15.9 |
| Hatay | 13.5 | 32.6 | 50.0 | 3.9 |
| Malatya | 11.7 | 26.9 | 58.1 | 3.3 |
| Kahramanmaraş | 11.2 | 21.7 | 52.3 | 14.9 |
| Kilis | 14.0 | 28.1 | 48.4 | 9.5 |
| Osmaniye | 10.5 | 25.7 | 46.5 | 17.3 |
| Şanlıurfa | 5.5 | 18.5 | 61.0 | 14.9 |
| Total - 11 Cities | 10.0 | 27.6 | 51.1 | 11.3 |
| Total Türkiye | 12.6 | 30.9 | 47.4 | 9.1 |

Source: SBB Report

Building types



Building function



Building damage information:

As of March 6th 2023

| | Total Number of Urgent + Severely Damaged + Collapsed Houses | Number of Moderately Damaged Houses | Number of Lightly Damaged Houses |
|---------------|--|-------------------------------------|----------------------------------|
| Adana | 2,952 | 11,768 | 71,072 |
| Adiyaman | 56,256 | 18,715 | 72,729 |
| Diyarbakır | 8,602 | 11,209 | 113,223 |
| Elazığ | 10,156 | 15,22 | 31,151 |
| Gaziantep | 29,155 | 20,251 | 236,497 |
| Kahramanmaraş | 99,326 | 17,887 | 161,137 |
| Malatya | 71,519 | 12,801 | 107,765 |
| Hatay | 215,255 | 25,957 | 189,317 |
| Kilis | 2,514 | 1,303 | 27,969 |
| Osmaniye | 16,111 | 4,122 | 69,466 |
| Şanlıurfa | 6,163 | 6,041 | 199,401 |
| Total | 518,009 | 131,577 | 1,279,727 |

Source: MoEUCC

| | billion USD |
|---|-------------|
| Damage¹ | |
| Reconstruction Cost of Unusable Housing | 54.7 |
| Reconstruction Cost of Unusable Barns | 0.2 |
| Reconstruction Cost of Unusable Businesses | 2 |
| Repair Assistance for Lightly Damaged Housing ² | 0.7 |
| Furniture Cost in Unusable Housing | 3.1 |
| Total Damage | 60.7 |
| Loss | |
| Debris Removal and Cleaning Cost ³ | 1.6 |
| Household Payments for Housing with Severe Damage + Requiring Urgent Demolition + Moderate Damage | 0.3 |
| Temporary Accommodation | 1.3 |
| Meal and Accommodation | 2.1 |
| Total Loss | 5.3 |
| Total Damage and Loss | 66 |

In light of this data, 2,273,551 people were directly faced with accommodation problem after the earthquake.

Besides, 14,314 farm barns were determined as severely damaged, demolished, or requiring urgent demolition in the earthquake-affected region. The total damage to farm and businesses 2.2 billion USD.


Education system:

11,699 educational institutions (21% of Türkiye). The institutions have 20,340 independent buildings, including various annexes such as lodging houses, sports halls, and workshops.

| Provinces | Kindergarten | Primary School | Secondary School | High School | Teachers' Guest-house | Public Education Centre | Vocational Education Centre | Special Education Practice School + CRC | Total |
|---------------------|--------------|----------------|------------------|-------------|-----------------------|-------------------------|-----------------------------|---|---------------|
| Adana | 157 | 490 | 321 | 220 | 16 | 20 | 5 | 30 | 1,259 |
| Adıyaman | 78 | 402 | 215 | 88 | 7 | 9 | 4 | 21 | 824 |
| Diyarbakır | 129 | 851 | 419 | 179 | 21 | 17 | 5 | 23 | 1,644 |
| Gaziantep | 233 | 572 | 352 | 212 | 9 | 11 | 7 | 30 | 1,426 |
| Elazığ | 36 | 185 | 127 | 72 | 8 | 10 | 5 | 8 | 451 |
| Hatay | 165 | 558 | 415 | 160 | 12 | 15 | 5 | 38 | 1,368 |
| Kahramanmaraş | 69 | 440 | 295 | 145 | 8 | 12 | 4 | 23 | 996 |
| Kilis | 20 | 98 | 42 | 25 | 1 | 5 | 2 | 9 | 202 |
| Malatya | 60 | 272 | 210 | 111 | 7 | 13 | 1 | 12 | 686 |
| Osmaniye | 42 | 164 | 113 | 63 | 3 | 7 | 4 | 17 | 413 |
| Şanlıurfa | 179 | 1260 | 712 | 219 | 9 | 13 | 5 | 33 | 2,430 |
| Total Region | 1168 | 5292 | 3221 | 1494 | 101 | 132 | 47 | 244 | 11,699 |

Source: MoNE


**School buildings
(8,162 out of 20,340)**



Loss for the education system: 2.11 billion USD.

Health care system:

- 116 secondary- and tertiary-level healthcare facilities (12.5% of Türkiye).
- 2503 primary-level healthcare facilities (17.5% of Türkiye).
- Total patient bed capacity 7,806.
- 31.3 beds/ 10,000 people (< average of Türkiye = 32.3 beds / 10,000 people)




Total loss to the health sector: 4.3 billion USD

Cultural heritage:

Ministry of Culture (MoCT) owns 8,444 inventory of cultural heritage

| | Protected streets | Monuments | Administrative building | Culture structure | Military structures | Industry and commercial structures | Religious structures | Cemeteries | Civil architectures | Ruins | Total |
|---------------|-------------------|-----------|-------------------------|-------------------|---------------------|------------------------------------|----------------------|------------|---------------------|-------|-------|
| Adana | 3 | 1 | 54 | 143 | 39 | 85 | 75 | 61 | 320 | 95 | 876 |
| Adiyaman | - | 2 | 2 | 46 | 6 | 7 | 54 | 14 | 8 | 25 | 164 |
| Diyarbakır | - | - | 70 | 261 | 11 | 4 | 153 | 93 | 606 | 22 | 1220 |
| Elazığ | - | 1 | 36 | 89 | 5 | - | 72 | 23 | 80 | 9 | 315 |
| Gaziantep | - | 4 | 36 | 95 | 6 | 22 | 77 | 36 | 797 | 8 | 1081 |
| Hatay | 2 | 3 | 50 | 144 | 16 | 53 | 114 | 88 | 576 | 62 | 1108 |
| Kahramanmaraş | - | 9 | 5 | 58 | 25 | 41 | 46 | 33 | 327 | 17 | 561 |
| Kilis | - | 2 | 5 | 28 | 5 | 13 | 35 | 4 | 356 | 4 | 452 |
| Malatya | - | 4 | 23 | 119 | 5 | 14 | 99 | 37 | 454 | 10 | 765 |
| Osmaniye | - | 1 | 13 | 24 | 8 | 1 | 19 | 28 | 45 | 26 | 165 |
| Şanlıurfa | 14 | 1 | 26 | 155 | 7 | 13 | 120 | 76 | 1301 | 24 | 1737 |
| Total | 19 | 28 | 320 | 1162 | 133 | 253 | 864 | 493 | 4870 | 302 | 8444 |

Cultural heritage (2,863 out of 8,444)



Total loss to the culture heritage:
489 million USD

■ Collapsed ■ Severe damage ■ Moderate damage ■ Lightly damage ■ No damage

Social and Economical impacts:

- 11 major city centres and 14 million people were affected.
- A total of 50,783 people lost their lives, and 115,353 people were injured.
- The number of collapsed or urgently demolished buildings in the region is reported as 58,039, while the number of severely damaged buildings is 205,534 (May 2, 2023).
- Housing sector: 56.9 billion USD
- Deconstruction sector: 12.9 billion USD
- Private industries (including manufacturing, energy, communications, tourism, healthcare, education sectors): 11.8 billion USD
- Other insurance section
- Total economy loss: 103.6 billion USD (~9% of GDP of Türkiye in 2023)

| TIME | TITLE | SPEAKER(s) |
|--------------------|--|--|
| 1:20 - 1:40 | Seismology and Geotechnical Effects | Alemdar Bayraktar, Visiting Professor, UBC (Remote) Keshab Sharma, Geotechnical Engineer, BGC Engineering Inc. (Remote) Carlos Ventura, Professor, UBC |
| 1:40 - 2:00 | Building Codes and Construction Practices | Tony Yang, Professor, UBC |
| 2:00 - 2:20 | Break | |
| 2:20 - 2:40 | Performance of Residential Buildings | Svetlana Brzev, Adjunct Professor, UBC |
| 2:40 - 3:00 | Performance of Schools Buildings | Bishnu Pandey, Instructor, BCIT Allison Chen, Practice Advisor, EGBC |
| 3:00 - 3:20 | Performance of Health Care Facilities | Jeffrey Salmon, Structural Engineer, Ausenco |
| 3:20 - 3:40 | Break | |
| 3:40 - 4:20 | Preparedness, Response, and Recovery | Allison Chen, Practice Advisor, EGBC Jeffrey Salmon, Structural Engineer, Ausenco Serife Ozata, Research, teaching assistant, Ahi Evran University (Remote) |
| 4:20 - 4:50 | Panel Discussion | |
| 4:50 - 5:00 | Concluding Remarks | Tony Yang, Professor, UBC |

2.

Seismology and Geotechnical Effects

Alemdar Bayraktar, Visiting Professor, UBC Civil Engineering Department
Keshab Sharma, Geotechnical Engineer, BGC Engineering Inc.
Carlos E. Ventura, Professor, UBC Civil Engineering Department



Content


- Global and Local Seismic Hazard Maps of Turkey
- Active Faults of Turkey
- Historical Seismicity of Turkey
- Main and Aftershocks of the February 2023 Kahramanmaraş Earthquakes
- Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes
- Conclusions

Global and Local Seismic Hazard Maps of Turkey

Global Earthquake Model




Global Seismic Hazard Map






Turkey is located in one of the most seismically active regions in the world.

Global and Local Seismic Hazard Maps of Turkey



from AFAD




from AFAD


The seismicity parameters are defined depending on the geographic location in TEC (2018) for the four seismic levels as follows:

- i) DD-1: 2 percent probability of exceedance within a 50-year period having a return period of 2475 years
- ii) DD-2: 10 percent probability of exceedance within a 50-year period having a return period of 475 years
- iii) DD-3: A earthquake with 50 percent probability of exceedance within a 50-year period having a return period of 72 years
- iv) DD-4: A earthquake with 68 percent probability of exceedance within a 50-year period having a return period of 43 years

Active Faults of Turkey




from USGS (2023)



from Emre et al. (2013), MTA (2023)

- Turkey is located between the Eurasian Plate in the north and the African-Arabian Plates in the south.
- The Arabian plate is moving towards the northeast with respect to the Anatolian plate at approximately 10-11 mm/yr.
- Two main major faults of Turkey are North Anatolian Fault (NAF) and East Anatolian Fault (EAF). The 2023 Kahramanmaraş earthquakes occurred on the EAF.
- The north Anatolian fault lies between Karlıova and Istanbul.
- The fault mechanism of the East Anatolian Fault Zone (EAFZ), which is about 450km long, is NE-trending left-lateral strike-slip fault system that lies between Karlıova and Hatay.

Historical Seismicity of Turkey




The last destructive earthquake in the city of Kahramanmaraş and its surroundings occurred approximately 500 years ago. A destructive earthquake has been anticipated in this area for a long time.

- The most damaging prior earthquakes in Turkey since the beginning of the 20th century are the 1939 M7.8 Erzincan and the 1999 M7.6 İzmit (Kocaeli) earthquakes, which occurred on the North Anatolian Fault.
- The 1939 Erzincan earthquake killed more than 32,000 people and injured more than 100,000, whereas the 1999 İzmit (Kocaeli) earthquake killed more than 17,000 and injured more than 50,000.
- From the year 2000 to the February 6, 2023, Kahramanmaraş earthquakes, the following destructive earthquakes occurred on the East Anatolian Fault:
 - On May 1, 2003, in Bingöl with a magnitude of 6.3
 - On March 14, 2005, in Karlıova (Bingöl) (M5.8)
 - On February 21, 2007, in Doğanyol (Malatya) (M5.7)
 - On March 8, 2010, in Kovancılar (Elazığ) (M6.1)
 - On January 24, 2020, in Sivrice (Elazığ) (M6.8)
 - On June 14, 2020, in Karlıova (Bingöl) (M5.7)

Main and Aftershocks of the February 2023 Kahramanmaraş Earthquakes

Multiple fault ruptures




- In the M7.7 Pazarcık earthquake, multiple fault segments associated with the East Anatolian Fault (Narlı, Gölbaşı, Erkenek, and Amanos faults) ruptured in a multi-segmented manner (AFAD, 2023).
- In the M7.6 Elbistan earthquake, it has been evaluated that both the Çardak and Doğanşehir faults ruptured simultaneously (AFAD, 2023).
- After both earthquakes, surface deformations ranging from centimeters to 4 meters have been detected (AFAD, 2023).



from USGS (2023) and EERI (2023)


Main and Aftershocks of the February 2023 Kahramanmaraş Earthquakes

Earthquake epicenters and fault lines near the city and town centers, and , and shallow earthquakes



- The earthquakes mostly affected the cities of Kahramanmaraş, Hatay, Adıyaman, Gaziantep, Malatya, Kilis, Diyarbakır, Adana, Osmaniye, Şanlıurfa and Elazığ with residents of over 14 million, and north part of Syria.
- Due to the earthquakes the 2023 Kahramanmaraş earthquakes, a total of 50,783 people lost their lives, and 115,353 people were injured.
- According to the damage assessment dated May 2, 2023, from the Ministry of Environment, Urbanization, and Climate Change, the number of collapsed or urgently demolished buildings in the region is reported as 58,039, while the number of severely damaged buildings is 205,534.
- These figures exceed the losses experienced in the 1939 Erzincan earthquake (M7.9) and the 1999 Kocaeli earthquake (M7.6), which were the largest earthquakes in our country in this century.



Ground Motion Records from the February 2023 Kahramanmaraş Earthquakes



The strong ground motion data of the February 2023 Kahramanmaraş earthquakes recorded by the Turkish Accelerometric Database and Analysis System (TADAS) (<https://tadas.afad.gov.tr>), which is operated by AFAD (Disaster and Emergency Management Presidency) by using more than 800 strong motion stations in Turkey.

Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes

Comparing horizontal and vertical PGAs with the previous earthquakes in Turkey




The peak horizontal and vertical ground acceleration values of the 2023 Kahramanmaraş earthquake are larger than the highest horizontal and vertical ground acceleration values of the 1999 Kocaeli and the other earthquakes in Turkey, respectively.

Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes

Recorded PGAs at selected stations during the M7.8 earthquake


| İstasyon Kodu | Boylam | Enlem | İl | İlçe | R _{jb} (km) | R _{rup} (km) | R _{epi} (km) | R _{hyp} (km) | V _{s,30} (m/s) | Zemin Sınıfı | PGA_NS (cm/s ²) | PGA_EW (cm/s ²) | PGA_UD (cm/s ²) |
|---------------|---------|---------|---------------|--------------|----------------------|-----------------------|-----------------------|-----------------------|-------------------------|--------------|-----------------------------|-----------------------------|-----------------------------|
| 3129 | 36.1343 | 36.1912 | Hatay | Defne | 214.65 | 214.65 | 146.39 | 146.64 | 447.0 | ZC | 1350.49 | 1207.62 | 707.55 |
| 3126 | 36.1375 | 36.2202 | Hatay | Antakya | 211.96 | 211.96 | 143.54 | 143.80 | 350.0 | ZD | 1211.04 | 1030.18 | 1071.45 |
| 3141 | 36.2197 | 36.3726 | Hatay | Antakya | 194.26 | 194.26 | 125.42 | 125.71 | 338.0 | ZD | 961.12 | 868.82 | 722.66 |
| 3125 | 36.1326 | 36.2381 | Hatay | Antakya | 210.71 | 210.71 | 142.15 | 142.41 | 448.0 | ZC | 822.62 | 1121.95 | 1151.56 |
| 3135 | 35.8831 | 36.4089 | Hatay | Arsuz | 212.40 | 212.40 | 142.15 | 142.41 | 460.0 | ZC | 740.97 | 1372.07 | 588.97 |
| 2718 | 36.6266 | 37.0078 | Gaziantep | İslahiye | 22.76 | 22.76 | 48.30 | 49.06 | - | - | 702.42 | 644.97 | 585.79 |
| 3123 | 36.1597 | 36.2142 | Hatay | Antakya | 211.22 | 211.22 | 143.00 | 143.26 | 470.0 | ZC | 655.57 | 593.94 | 867.58 |
| 4616 | 36.8384 | 37.3755 | Kahramanmaraş | Türkoğlu | 81.78 | 81.78 | 20.54 | 22.27 | 390.0 | ZC | 652.76 | 502.87 | 397.27 |
| 3142 | 36.3661 | 36.4980 | Hatay | Kırıkhan | 175.15 | 175.15 | 106.49 | 106.84 | 539.0 | ZC | 646.63 | 749.51 | 505.89 |
| NAR | 37.1574 | 37.3919 | Kahramanmaraş | Pazarcık | 55.60 | 55.60 | 15.35 | 17.60 | - | - | 646.50 | 578.80 | 398.66 |
| 3145 | 36.4064 | 36.6454 | Hatay | Kırıkhan | 160.58 | 160.58 | 91.13 | 91.54 | 533.0 | ZC | 600.04 | 696.39 | 663.18 |
| 4615 | 37.1380 | 37.3868 | Kahramanmaraş | Pazarcık | 57.36 | 57.36 | 13.83 | 16.28 | 484.0 | ZC | 587.74 | 556.46 | 664.58 |
| 3139 | 36.4144 | 36.5838 | Hatay | Kırıkhan | 165.13 | 165.13 | 96.19 | 96.57 | 272.0 | ZD | 577.13 | 504.82 | 378.62 |
| 3124 | 36.1722 | 36.2387 | Hatay | Antakya | 208.40 | 208.40 | 140.11 | 140.37 | 283.0 | ZD | 572.63 | 638.32 | 578.08 |
| 2712 | 36.7328 | 37.1840 | Gaziantep | Nurdağı | 99.71 | 99.71 | 29.79 | 31.01 | - | - | 554.85 | 602.66 | 346.12 |
| 3136 | 36.2472 | 36.1159 | Hatay | Altınözü | 215.21 | 215.21 | 148.38 | 148.63 | 344.0 | ZD | 534.22 | 401.97 | 220.46 |
| 3132 | 36.1716 | 36.2067 | Hatay | Antakya | 211.21 | 211.21 | 143.12 | 143.38 | 377.0 | ZC | 515.31 | 514.63 | 354.18 |
| 2715 | 36.6856 | 36.8554 | Gaziantep | İslahiye | 27.39 | 27.39 | 57.62 | 58.25 | - | - | 456.12 | 340.76 | 263.92 |
| 3137 | 36.4885 | 36.6929 | Hatay | Hassa | 151.71 | 151.71 | 82.48 | 82.93 | 688.0 | ZC | 453.09 | 848.01 | 501.98 |
| 4625 | 36.9819 | 37.5387 | Kahramanmaraş | Dulkadiroğlu | 64.43 | 64.43 | 28.40 | 29.67 | 346.0 | ZD | 448.15 | 483.65 | 367.37 |
| 3131 | 36.1633 | 36.1912 | Hatay | Antakya | 213.03 | 213.03 | 144.98 | 145.23 | 567.0 | ZC | 363.03 | 366.05 | 153.96 |



Recorded PGAs Recorded PGAs during the M7.5 earthquake




| İstasyon Kodu | Boylam | Enlem | İl | İlçe | R _{jb} (km) | R _{rup} (km) | R _{epi} (km) | R _{hyp} (km) | V _{s,30} (m/s) | Zemin Sınıfı | PGA_NS (cm/s ²) | PGA_EW (cm/s ²) | PGA_UD (cm/s ²) |
|---------------|---------|---------|---------------|---------------|----------------------|-----------------------|-----------------------|-----------------------|-------------------------|--------------|-----------------------------|-----------------------------|-----------------------------|
| 4612 | 36.4819 | 38.0240 | Kahramanmaraş | Göksun | 94.52 | 94.52 | 66.68 | 67.05 | 246.0 | ZD | 635.45 | 523.21 | 494.91 |
| 4406 | 37.9738 | 38.3439 | Malatya | Akçadağ | 109.15 | 109.15 | 70.17 | 70.52 | 815.0 | ZB | 467.20 | 409.31 | 318.75 |
| 0131 | 36.1153 | 37.8566 | Adana | Saimbeyli | 130.83 | 130.83 | 101.83 | 102.07 | - | - | 402.32 | 331.69 | 85.29 |
| 4409 | 37.4908 | 38.5606 | Malatya | Darende | 114.09 | 114.09 | 56.86 | 57.28 | - | - | 287.04 | 218.04 | 124.28 |
| 3802 | 36.5036 | 38.4781 | Kayseri | Sarız | 66.94 | 66.94 | 77.41 | 77.73 | 305.0 | ZD | 195.79 | 220.88 | 122.81 |
| 4611 | 37.2843 | 37.7472 | Kahramanmaraş | Çağlayancerit | 97.41 | 97.41 | 38.21 | 38.85 | 731.0 | ZC | 194.40 | 139.04 | 72.57 |
| 4614 | 37.2978 | 37.4851 | Kahramanmaraş | Pazarcık | 126.57 | 126.57 | 67.35 | 67.71 | 671.0 | ZC | 160.82 | 206.05 | 89.21 |
| 4412 | 38.1839 | 38.5969 | Malatya | Yazihan | 142.61 | 142.61 | 99.89 | 100.14 | - | - | 159.03 | 126.38 | 79.90 |
| 4405 | 37.9396 | 38.8107 | Malatya | Hekimhan | 152.67 | 152.67 | 100.81 | 101.05 | 579.0 | ZC | 155.41 | 158.05 | 121.88 |
| 0129 | 36.2109 | 38.2592 | Adana | Tufanbeyli | 99.27 | 99.27 | 91.84 | 92.11 | 965.0 | ZB | 154.46 | 172.18 | 83.75 |

from GTU (2023)



Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes






High PGAs



- During the **M7.8** earthquake,
 - the first PGA at Pazarçık station TK4614 ($V_s=541$ m/s) was measured in the east-west direction as **2039.20 cm/s^2** ($R_{epi}=31.42\text{km}$)
 - the second PGA was recorded at Hatay station TK3129 ($V_s=447$ m/s, ZC) was recorded in the north-south direction as **1351.50 cm/s^2** ($R_{epi}=146.39$ km).
- During the **M7.5** earthquake, the PGA at Göksun station TK4612 ($V_s=246$ m/s, ZD) was measured in the north-south direction as **635.45 cm/s^2** ($R_{epi}=66.68$ km).
- During the **M6.4** earthquake, the PGA at Hatay station TK 3125 ($V_s=448$ m/s, ZC) was recorded in the north-south direction as **775.40 cm/s^2** ($R_{epi}=24.50$ km).






Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes

Characteristics of maximum accelerations recorded at TK3129 Hatay (Defne) station during the M7.8 earthquake










Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes

Characteristics of maximum accelerations recorded at TK4612 Kahramanmaraş (Göksun) station during the M7.5 earthquake




Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes



Pulse-like ground velocity and high PGV were recorded during the the 2023 earthquakes.

From Dr. Iunio Iervolino

Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes



- The design response spectra for residential buildings (i.e. maximum design earthquake with a return period of 475 years) are exceeded for a wide period range, whereas the maximum credible earthquake level (return period of 2475 years) response spectra is generally exceeded for long periods especially in soft soils, in certain regions.
- Buildings having periods around of 0.5-2s completely collapsed or heavily damaged.
- This implies that the buildings in Gaziantep (İslahiye and Nurdağı districts), Hatay, Kahramanmaraş, and Adıyaman were subjected to seismic actions larger than Turkish Earthquake Code design levels.

Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes

Comparison of damages and PGAs, PGVs, and PGDs recorded at stations in Hatay (Antakya), located approximately 150km from the epicenter, during the 2023 earthquakes



TK3126 (Vs= 350 m/s), TK3123 (Vs= 470m/s), TK3132 (Vs= 377 m/s), TK3129 (Vs= 447 m/s)

Ground Motion Characteristics of the February 2023 Kahramanmaraş Earthquakes



<https://www.linkedin.com/feed/update/urn:li:activity:7034080118608125952/>

Content

In addition to design and construction phases mistakes, there are some reasons due to the seismic characteristics of the 2023 earthquakes for the extensive damages and collapses of a large number of buildings:

- High seismic intensity ((large PGA, PGV, PGD and spectral values),
- Earthquake sequence (back-to-back events),
- Near-fault effects, basin effects, soil amplification
- Shallow earthquakes (less than 10km deep),
- Long duration of the ground shaking,
- Epicenters proximity to many of the cities severely affected,
- Proximity of several cities to the faults that caused the events,
- Very long ruptured fault systems,
- Different ruptured fault segments,
- Underestimation of the seismic demands during the design process

Geotechnical observations


- Surface Rupture
- Liquefaction and Subsidence
- Performance of Dam

Surface Rupture

Fault rupture on multiple segment of the faults that crosses infrastructures (i.e., highway, pipelines, buildings)



Islahiye



Taftsoглу et al. 2023

Surface Rupture in Islahiye


The fault zone becomes 10-50 m in width in a N30°E direction



Liquefaction and Subsidence

Liquefaction is the process by which the soil below the water table temporarily lose its strength during earthquake and behave as a viscous liquid rather than soil.

- Liquefied sites were along the faults line at several locations
- Widespread liquefaction on wetlands and along the costal line
- Liquefaction induced ground and structural failures were widespread in some cities




Taftoglou et al. 2023

Liquefaction and Subsidence

Golbasi


- City built up after the 1950s on a former wetland
- Compressible wetland sediments up to 21 m thick
- Liquefaction induced ground failures were widespread in several cities



Taftoglou et al. 2023

Liquefaction and Subsidence


Golbasi



Source: GDM lab, u of Tokyo

| ERA | PERIOD | EPOCH | FORMATION | LITHOLOGY | DESCRIPTION | |
|----------|------------------|----------------|-----------------|---|--|------|
| CENOZOIC | QUATERNARY | | | Marsh Sediments (Qb) Slopewash (Qy) Alluvial deposits (Qal) | A.U. | |
| | | TERTIARY | PAZARCIK | | Loose poorly consolidated conglomerate, silt, mudstone | A.U. |
| | | | DÖNDÜKLER | | Abundant chalky, poorly consolidated claystone marl and highly porous limestone bands intercalation Red mudstone, white chalky claystone and marl intercalation | |
| | Pliocene | ESMEPURU | | Red brownish, light gray conglomerate, sandstone, mudstone intercalation | | |
| | | HOYA | | A.U. Cream, light gray, white colored, locally dolomitic limestone with abundant fossils | A.U. | |
| | | MESOZOIC | GERMAV | | Thin-bedded, bluish green claystone-marl, sandstone intercalation Green shale, claystone and marl intercalation | |
| | | | KARADUT COMPLEX | | A.U. Silicified limestones, cherty siliceous manganese shale claystone-marl, limestone | |
| | UPPER CRETACEOUS | KOÇALI COMPLEX | | Ultrabasic rocks, serpentinites, volcanics | | |
| | | | | A.U.: Angular Uncorformity | | |

Akil et al. 2023



Liquefaction and Subsidence

Golbasi



Liquefaction and Subsidence


Golbasi Lake



Liquefaction and Subsidence

Iskenderun


- Young marine deposits and fills dominate the coastal plains.
- Soils along the coastal area include loose to medium dense sands and silty sands.
- Soil conditions are highly variable because of the marine and alluvial depositional environment, as well as the reclamation fill.
- Severely damaged due to widespread lateral spreading and liquefaction along its coastal front.



Özdemir and Şahinoğlu, 2018

Liquefaction and Subsidence

Iskenderun



Source: GDM lab, u of Tokyo



Land reclamation using liquefiable material is problematic.

Performance of Dam

Kartalkaya dam

- A clay core earthfill dam constructed in 1972 in Kahramanmaraş
- Crest height from the stream level is 56 meters and store 1.45 million m³ water.
- Dam is 3 km away from the epicenter of the first event.
- Moderate damage with crack widths varying in between 15-35 cm was observed along the crest of the dam



Conclusions

- Fault rupture on multiple segment of the faults that crossed and damaged the infrastructures.
- Widespread liquefaction on wetlands and along the costal line
- Liquefaction induced severe damage was observed in Golbasi and Iskenderun.
- Embankment dams exhibited varied performance based on several factors.
- Land reclamiation using liquefiable material is problematic. Seismic microzonation and land use planning are key factors.
- Several locations in Western Canada including Vancouver (along the costal line and river) are highly vulnerable to liquefaction and can cause several damage to infrastructures.

Key Message

- Seismic microzonation and land use planning are key factors.
- Land reclamation using liquefiable material is problematic.
- Geotechnical consideration is equally important as structural design.

3.

Building codes in Turkey

Tony T.Y. Yang, Ph.D., P.Eng., F.CAE, Professor, UBC

Alemdar Bayraktar, Visiting Professor, UBC


Svetlana Brzev, Ph.D., P.Eng., FEC, Adjunct Professor, UBC



Introduction:


- Many large earthquakes occurred in 1940s to early 2000s have resulted in more than 100,000 deaths, 200,000 injuries, and the destruction of 750,000 buildings before the February 6, 2023 Kahramanmaraş earthquakes. These earthquakes have shaped the fundamental of the seismic design codes in Turkey.

History:



1944 Turkish building code:

- First seismic hazard map in Turkey
- 3 zones: Red (0.1 W), Yellow (0.05 W), White (0 W)
- Base shear was distributed over the height of the building using a uniform load pattern



1949 Turkish building code:

- Live load was included in the calculation of the weight of the building:


$$W = \sum w_i \quad w_i = g_i + n p_i$$

where w_i is the weight of the i th floor, g_i is the dead load of the i th floor, n is a live load coefficient (equal to 0.33 for houses, 0.5 for commercial buildings, and 1.0 for high-occupancy buildings), and p_i is the live load of the i th floor.

- 3 zones:
 - Red ($0.1 W \rightarrow 0.04$ to $0.02 W$, base on building height)
 - Yellow ($0.05 W \rightarrow 0.03$ to $0.01 W$, based on building height)
 - White ($0 W$)
- 1953 Turkish building code remains similar to the 1949 Turkish building code.

1962 Turkish building code:

- A new seismic hazard map in Turkey
- 4 zones



- Base shear coefficient:

$$C = C_0 n_1 n_2$$

where $C_0 = 0.10$ to 0.06 (depends on building height),

n_1 and n_2 depends on building material (steel or reinforced concrete), soil classifications, and earthquake zone.

- For heights greater than 40 m, C_0 was increased by 0.01 for every 3.0 m above 40 m.

1968 Turkish building code:

- Made significant changes to the seismic design:
 - Introducing the requirement for detailing of RC structure
 - Use spectra shape & dynamic effect to quantify the earthquake load
 - Introduce important factor

- Base shear:

$$C = C_0 \alpha \beta \gamma$$

where C_0 is a seismic zone coefficient:

Zone 1: 0.06; Zone 2: 0.04; Zone 3: 0.02; Zone 4: 0

α is a soil coefficient:

Rock: 0.80; Sand, gravel, and hard clay : 1.00; other loose soil containing water or poor soils: 1.20;

β is the importance factor:

critical, high-occupancy, or historically important buildings: 1.50

otherwise: 1.00;

γ was a dynamic coefficient:

max (0.5/T, 0.3) for $T > 0.50$ sec $T = 0.09 \frac{H}{\sqrt{D}}$, H = height and D = width of the building

1.00 for $T \leq 0.5$ sec

- $F_i = V \frac{w_i h_i}{\sum_i w_i h_i}$, where h_i is the height of the floor above the foundation.


1998 Turkish building code:

- Consider as the 1st modern building code in Turkey.
- A new seismic hazard map
- Base shear: $A(T) = A_0 I S(T)$

Zone factor (A_0): Zone 1 = 0.4; Zone 2 = 0.3; Zone 3 = 0.2; Zone 4 = 0.1; Zone 5 = 0

I is importance factor:

| Purpose of Occupancy or Type of Building | Importance Factor (I) |
|---|-----------------------|
| 1. Buildings to be utilised after the earthquake and buildings containing hazardous materials a) Buildings required to be utilised immediately after the earthquake (Hospitals, dispensaries, health wards, fire fighting buildings and facilities, PTT and other telecommunication facilities, transportation stations and terminals, power generation and distribution facilities; governorate, county and municipality administration buildings, first aid and emergency planning stations) b) Buildings containing or storing toxic, explosive and flammable materials, etc. | 1.5 |
| 2. Intensively and long-term occupied buildings and buildings preserving valuable goods a) Schools, other educational buildings and facilities, dormitories and hostels, military barracks, prisons, etc. b) Museums | 1.4 |
| 3. Intensively but short-term occupied buildings Sport facilities, cinema, theatre and concert halls, etc. | 1.2 |
| 4. Other buildings Buildings other than above defined buildings. (Residential and office buildings, hotels, building-like industrial structures, etc.) | 1.0 |




| Local Site Class acc. to Table 12.2 | T_A (second) | T_B (second) |
|-------------------------------------|----------------|----------------|
| Z1 | 0.10 | 0.30 |
| Z2 | 0.15 | 0.40 |
| Z3 | 0.15 | 0.60 |
| Z4 | 0.20 | 0.90 |

$$S(T) = 2.5 (T_B / T)^{0.8}$$

AFET İŞLERİ GENEL MÜDÜRLÜĞÜ
DEPREM ARAŞTIRMA DAİRESİ

1998 Turkish building code:

- Deals with irregularities







In the case where floors behave as rigid diaphragms in their own planes:

$$(\Delta_i)_{\text{ort}} = 1/2 [(\Delta_i)_{\max} + (\Delta_i)_{\min}]$$

Torsional irregularity factor :

$$\eta_{\text{bi}} = (\Delta_i)_{\max} / (\Delta_i)_{\text{ort}}$$

Torsional irregularity : $\eta_{\text{bi}} > 1.2$



1998 Turkish building code:

➤ Reduction factor

| <i>BUILDING STRUCTURAL SYSTEM</i> | <i>Systems of Nominal Ductility Level</i> | <i>Systems of High Ductility Level</i> |
|---|---|--|
| <u>(1) CAST-IN-SITU REINFORCED CONCRETE BUILDINGS</u> | | |
| (1.1) Buildings in which seismic loads are fully resisted by frames..... | 4 | 8 |
| (1.2) Buildings in which seismic loads are fully resisted by coupled structural walls..... | 4 | 7 |
| (1.3) Buildings in which seismic loads are fully resisted by solid structural walls..... | 4 | 6 |
| (1.4) Buildings in which seismic loads are jointly resisted by frames and solid and/or coupled structural walls..... | 4 | 7 |
| <u>(2) PREFABRICATED REINFORCED CONCRETE BUILDINGS</u> | | |
| (2.1) Buildings in which seismic loads are fully resisted by frames with connections capable of cyclic moment transfer | 3 | 6 |
| (2.2) Buildings in which seismic loads are fully resisted by single-storey hinged frames with fixed-in bases..... | — | 5 |
| (2.3) Buildings in which seismic loads are fully resisted by prefabricated solid structural walls..... | — | 4 |
| (2.4) Buildings in which seismic loads are jointly resisted by frames with connections capable of cyclic moment transfer and cast-in-situ solid and/or coupled structural walls | 3 | 5 |
| <u>(3) STRUCTURAL STEEL BUILDINGS</u> | | |
| (3.1) Buildings in which seismic loads are fully resisted by frames..... | 5 | 8 |
| (3.2) Buildings in which seismic loads are fully resisted by single-storey hinged frames with fixed-in bases..... | 4 | 6 |
| (3.3) Buildings in which seismic loads are fully resisted by braced frames or cast-in-situ reinforced concrete structural walls | | |
| (a) <i>Centrally braced frames</i> | 3 | — |
| (b) <i>Eccentrically braced frames</i> | — | 7 |
| (c) <i>Reinforced concrete structural walls</i> | 4 | 6 |
| (3.4) Buildings in which seismic loads are jointly resisted by frames and braced frames or cast-in-situ reinforced concrete structural walls | | |
| (a) <i>Centrally braced frames</i> | 4 | — |
| (b) <i>Eccentrically braced frames</i> | — | 8 |
| (c) <i>Reinforced concrete structural walls</i> | 4 | 7 |

$$R_a(T) = 1.5 + (R - 1.5) T / T_A \quad (0 \leq T \leq T_A)$$

$$R_a(T) = R$$

1998 Turkish building code:

- Dynamic analysis methods
Methods such as mode superposition and Time history analysis

- Requirement to check drift limits

$$(\Delta_i)_{\max} / h_i \leq 0.0035$$

$$(\Delta_i)_{\max} / h_i \leq 0.02 / R, \text{ where } h_i \text{ is } i\text{th the story height.}$$

- Minimum strength requirements

In all buildings to be built in seismic zones, concrete strength less than that of C16 (BS 16) shall not be used. However, it is mandatory to use C20 (BS 20) quality or higher strength concrete in buildings to be built in the first and second seismic zones. Reinforcing steel with strength exceeding that of S420 shall not be used reinforced concrete structural elements. The rupture strain of reinforcement to be used shall not be less than 10%.


- More detailing requirements

2007 Turkish building code:

- Minor change from the 1998 Turkish building code.
- Significant change include:
 - Chapter for assessment and retrofit for existing buildings
 - Different design earthquake levels and performance levels
 - Can use push over analysis and nonlinear dynamic analysis for building assessment.


2018 Turkish building code:

- Latest building code.
- New hazard map. More refined (by coordinate not by zone)



2018 Turkish building code:

- Latest building code.
- New hazard map. More refined (by coordinate not by zone)
- Covers RC buildings, RC prefabricated buildings, steel buildings, masonry buildings, timber buildings, cold form steel buildings, high rise buildings, base-isolated buildings, evaluation and retrofitting existing buildings.
- It does not cover other type of structures, such as, historical structures, lifeline structures, coastal and port structures.
- Account for the vertical spectra



2018 Turkish building code:

- Multiple design earthquake shaking intensities
 - DD-1: 2/50 hazard level. RT = 2475 years.
 - DD-2: 10/50 hazard level. RT = 475 years.
 - DD-3: 50/50 hazard level. RT = 72 years.
 - DD-4: 68/50 hazard level. RT = 43 years.

- Account for multiple soil conditions:
 - ZA, ZB, ZC, ZD, ZE and ZF

- Account for soil amplification factors:

$$S_{DS} = S_S F_S \quad \& \quad S_{D1} = S_1 F_1$$

| Local soil class | Local soil impact factor F_S for the short-period zone | | | | | |
|------------------|---|--------------|--------------|--------------|--------------|-----------------|
| | $S_s \leq 0.25$ | $S_s = 0.25$ | $S_s = 0.75$ | $S_s = 1.00$ | $S_s = 1.25$ | $S_s \geq 1.50$ |
| ZA | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 |
| ZB | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 |
| ZC | 1.3 | 1.3 | 1.2 | 1.2 | 1.2 | 1.2 |
| ZD | 1.6 | 1.4 | 1.2 | 1.1 | 1.0 | 1.0 |
| ZE | 2.4 | 1.7 | 1.3 | 1.1 | 0.9 | 0.8 |
| ZF | A site-specific soil behavior analysis will be conducted. | | | | | |

| Local soil class | Local soil impact factor F_1 for the 1s-period zone | | | | | |
|------------------|---|--------------|--------------|--------------|--------------|-----------------|
| | $S_1 \leq 0.10$ | $S_1 = 0.20$ | $S_1 = 0.30$ | $S_1 = 0.40$ | $S_1 = 0.50$ | $S_1 \geq 0.60$ |
| ZA | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 |
| ZB | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 |
| ZC | 1.5 | 1.5 | 1.5 | 1.5 | 1.5 | 1.4 |
| ZD | 2.4 | 2.2 | 2.0 | 1.9 | 1.8 | 1.7 |
| ZE | 4.2 | 3.3 | 2.8 | 2.4 | 2.2 | 2.0 |
| ZF | A site-specific soil behavior analysis will be conducted. | | | | | |

2018 Turkish building code:

➤ Building use classes and important factors

| Building Usage Class | Purpose of Building Usage | Building Importance Coefficient |
|----------------------|---|---------------------------------|
| BKS=1 | a) Hospitals, dispensaries, health center, fire buildings, communication buildings and facilities, transportation stations and terminals, energy production and distribution facilities, first aid and disaster relief facilities, and provincial, district governorship and municipality administration buildings b) Schools, other educational buildings and facilities, dormitories, military barracks, prisons, etc. c) Museums d) Buildings stored toxic, explosive, flammable, etc.. | 1.5 |
| BKS=2 | Shopping malls, sport facilities, cinemas, theatres, concert halls, places of worship, etc. | 1.2 |
| BKS=3 | Other buildings that do not fall within the definitions given for BKS=1 and BKS=2 (Residential and commercial buildings, hotels, building type industrial structures, etc.) | 1.0 |

➤ Seismic design class (DTS)


| Short Period Design Spectral Acceleration Coefficient (S_{Ds}) at Earthquake Ground Motion Level DD-2 | Building Usage Class | |
|---|----------------------|-------|
| | | BKS=1 |
| $S_{Ds} < 0.33$ | DTS=4a | DTS=4 |
| $0.33 \leq S_{Ds} \leq 0.50$ | DTS=3a | DTS=3 |
| $0.50 \leq S_{Ds} \leq 0.75$ | DTS=2a | DTS=2 |
| $0.75 \leq S_{Ds}$ | DTS=1a | DTS=1 |

➤ Building height classes

| Building High Class | Building Height Intervals Defined According to Building Height Categories and Earthquake Design Classes [m] | | |
|---------------------|---|------------------------|---------------------|
| | DTS = 1, 1a, 2, 2a | DTS = 3, 3a | DTS = 4, 4a |
| BYS=1 | $H_N > 70$ | $H_N > 91$ | $H_N > 105$ |
| BYS=2 | $56 < H_N < 70$ | $70 < H_N \leq 91$ | $91 < H_N \leq 105$ |
| BYS=3 | $42 < H_N < 56$ | $56 < H_N \leq 70$ | $56 < H_N \leq 91$ |
| BYS=4 | $28 < H_N \leq 42$ | $42 < H_N \leq 56$ | |
| BYS=5 | $17.5 < H_N \leq 28$ | $28 < H_N \leq 42$ | |
| BYS=6 | $10.5 < H_N \leq 17.5$ | $17.5 < H_N \leq 28$ | |
| BYS=7 | $7 < H_N \leq 10.5$ | $10.5 < H_N \leq 17.5$ | |
| BYS=8 | $H_N \leq 7$ | $H_N \leq 10.5$ | |

2018 Turkish building code:

- Multiple Performance levels:



Structural performance level (Celep and Güler, 2020)

2018 Turkish building code:

➤ Defined performance objectives:

a) **New RC Buildings**, Precast and Steel Buildings
(Except High Rise Buildings - $BYS \geq 2$)


| Earthquake Level | DTS = 1, 1a ⁽¹⁾ , 2, 2a ⁽¹⁾ , 3, 3a, 4, 4a | | DTS = 1a ⁽²⁾ , 2a ⁽²⁾ | |
|-----------------------|--|----------------------------|---|----------------------------|
| | Normal Performance Target | Evaluation/Design Approach | Advanced Performance Target | Evaluation/Design Approach |
| DD-3 (72 yrs) | - | - | LD | SGDT |
| DD-2 (475 yrs) | CD | DGT | CD | <u>DGT^(3,4)</u> |
| DD-1 (2475 yrs) | - | - | CD | SGDT |

b) New or Existing **High Rise Buildings** - $BYS = 1$


| Earthquake Level | DTS = 1, 2, 3, 3a, 4, 4a | | DTS = 1a, 2a | |
|------------------------|---------------------------|----------------------------|-----------------------------|----------------------------|
| | Normal Performance Target | Evaluation/Design Approach | Advanced Performance Target | Evaluation/Design Approach |
| DD-4 (43 yrs) | UU | DGT | - | - |
| DD-3 (72 yrs) | - | - | LD | SGDT |
| DD-2 (475 yrs) | CD | <u>DGT⁽³⁾</u> | CD | <u>DGT^(3,4)</u> |
| DD-1 (2475 yrs) | CP | ŞGDT | CD | SGDT |

c) Existing RC Buildings, Precast and Steel Buildings
(Except High Rise Buildings - $BYS \geq 2$)


| Earthquake Level | DTS = 1, 2, 3, 3a, 4, 4a | | DTS = 1a, 2a | |
|------------------|---------------------------|----------------------------|-----------------------------|----------------------------|
| | Normal Performance Target | Evaluation/Design Approach | Advanced Performance Target | Evaluation/Design Approach |
| DD-3 (72 yrs) | - | - | LD | SGDT |
| DD-2 (475 yrs) | CD | SDGT | - | - |
| DD-1 (2475 yrs) | - | - | CD | SGDT |



Controlled damage (CD)



Uninterrupted use (UU)



Collapse prevention (CP)

2018 Turkish building code:

➤ Defined performance objectives:



a) New base-isolated buildings- Superstructure

| Earthquake Level | DTS = 1, 2, 3, 3a, 4, 4a | | DTS = 1a, 2a | |
|------------------|---------------------------|----------------------------|-----------------------------|----------------------------|
| | Normal Performance Target | Evaluation/Design Approach | Advanced Performance Target | Evaluation/Design Approach |
| DD-2 (475 yrs) | LD | DGT | UU | DGT |
| DD-1 (2475 yrs) | - | - | - | - |

b) Existing buildings to be retrofitting by base isolation- Superstructure


| Earthquake Level | DTS = 1, 2, 3, 3a, 4, 4a | | DTS = 1a, 2a | |
|------------------|---------------------------|----------------------------|-----------------------------|----------------------------|
| | Normal Performance Target | Evaluation/Design Approach | Advanced Performance Target | Evaluation/Design Approach |
| DD-2 (475 yrs) | CD | DGT | LD | DGT |
| DD-1 (2475 yrs) | - | - | - | - |

c) New base-isolated buildings and Existing buildings to be retrofitting by base isolation - Base isolation system and substructure


| Earthquake Level | DTS = 1, 2, 3, 3a, 4, 4a | | DTS = 1a, 2a | |
|------------------|---------------------------|--|-----------------------------|--|
| | Normal Performance Target | Evaluation/Design Approach | Advanced Performance Target | Evaluation/Design Approach |
| DD-2 (475 yrs) | - | - | - | - |
| DD-1 (2475 yrs) | UU | ŞGDT ⁽¹⁾ – DGT ⁽²⁾ | UU | ŞGDT ⁽¹⁾ – DGT ⁽²⁾ |

⁽¹⁾ It will be applied for the isolation system


⁽²⁾ It will be applied for substructure



Controlled damage (CD)



Uninterrupted use (UU)



Collapse prevention (CP)

➤ Turkish Ministry of Health issue a law in 2013

- Hospital Buildings, located in seismic zones 1 and 2 with number of bed capacity over 100 should be constructed with base-isolation.
- As of 2017, there were 72 base-isolated structures (e.g., hospitals, schools, airport terminals) in Türkiye.


Reference:

Erdik, Mustafa, et al. "Seismic isolation code developments and significant applications in Turkey." *Soil Dynamics and Earthquake Engineering* 115 (2018): 413-437.



1998&2007 Turkish seismic design codes: High-Ductility columns

2018 Turkish seismic design code: High-Ductility columns



Tie spacing within the critical zone

$$s_c \geq 50 \text{ mm}$$

$$s_c \leq 100 \text{ mm}$$

$$s_c \leq b_{min}/3$$


$$s_c \geq 50 \text{ mm}$$

$$s_c \leq 150 \text{ mm}$$

$$s_c \leq b_{min}/3$$

$$s_c \leq 6\phi_t$$

Lap splice requirements




1998&2007 Turkish seismic design codes:
High-Ductility columns



CSA A23.3-14 design standard
Ductile moment-resisting frames (Rd=4.0)





Tie spacing within the critical zone




$s_t \geq 50 \text{ mm}$
 $s_t \leq 100 \text{ mm}$
 $s_t \leq b_{min}/3$


$\leq 6 d_w$
 $\leq 100 \text{ mm}$
 $\leq c/4$
 $\leq \text{confinement steel}$



$R_d = 4.0$




1998&2007 Turkish seismic design codes:
High-Ductility columns




max. $a_1 = 25\phi$
 (ϕ : transverse reinf. diameter)

$s_p \leq 200 \text{ mm}$
 $s_p \leq b_{min}/2$




CSA A23.3-14 design standard
Ductile moment-resisting frames (Rd=4.0)

Detailing of column ties




(a) Overlapping Hoops




(b) Cross-Ties

If $X \leq 600 \text{ mm}$ then $Y \leq 200 \text{ mm}$
 If $X > 600 \text{ mm}$ then $Y \leq X/3$ but $\leq 350 \text{ mm}$

1998&2007 Turkish seismic design codes:
High-Ductility beams



2014 Canadian standard CSA A23.3-14
Ductile moment-resisting frames ($R_d=4.0$)





1998&2007 Turkish seismic design codes:
High-Ductility Walls

CSA A23.3-14 design standard
Ductile shear walls (Rd=4.0)



Longitudinal steel area – boundary elements
Spacing of ties – plastic hinge zone
Spacing of cross-ties



$A_s \geq 0.0015 b_w l_w$
 $A_s \leq 0.06 \times \text{area of concentrated reinforcement region}$

Cross-ties (buckling prevention ties) – spacing:

- six longitudinal bar diameters;
- 24 tie diameters;
- one-half of the least dimension of the member.

**Hoops @ $s \leq 6 d_w$
 $\leq 24 d_{ho}$
 $\leq b/2$**

4. Performance of Residential Buildings

Svetlana Brzev, PhD, PEng, FEC, Adjunct Professor,
Department of Civil Engineering, University of British
Columbia



OUTLINE

- **Construction practice**
- **Design codes - implications on the seismic performance of RC buildings**
- **Causes of damage and failure: typical examples**
- **Conclusions**

RESIDENTIAL BUILDINGS: CONSTRUCTION PRACTICE (1/2)

Reinforced concrete (RC) construction prevalent in urban settlements.

- Major construction boom of high-rise RC buildings started after 2000

Common building typologies:

- Mid-rise buildings (up to 6 storeys)
- High-rise buildings (usually 10 - 15 storeys)



RESIDENTIAL BUILDINGS: CONSTRUCTION PRACTICE (2/2)

Masonry construction found in historic areas of urban settlements, and in rural areas.

- Usually low-rise buildings for single-family housing
- Mostly unreinforced masonry buildings, vulnerable to seismic effects
- Stone and adobe (mud) masonry buildings experienced damage.

Focus of this presentation is on urban reinforced concrete residential buildings.



Credit: Şerife Ozata

SEISMIC DESIGN CODES - IMPLICATIONS ON THE DESIGN OF RC BUILDINGS

Turkish seismic design codes - published in **1998, 2007, and 2018**

The corresponding standard for reinforced concrete design TS500 - published in **1981 and 2000 (R2003)**

1998 Code - based on the 1996 seismic hazard map

- Prescribes nominal and high-ductility RC structures; the Capacity Design requirements introduced for the first time;
- Minimum column/beam dimension 25 cm (commonly used in practice);
- Shear walls - min thickness 20 cm; boundary elements required for high-ductility structures.

2007 Code - based on the 1996 seismic hazard map



- No significant changes in terms of the design and detailing of RC structures compared to the 1998 code;

2018 Code - new seismic hazard map

- More advanced, modern code (major changes);


DETAILING REQUIREMENTS FOR HIGH-DUCTILITY RC COLUMNS (1998 AND 2007 CODES)

- 135-degree hooks for ties, except for **cross-ties** (90-degree + 135-degree hooks);
- **Closer tie spacing** within the end zones
- Lap splice length near beam-column joints increased by 25-50% relative to the basic development length.



DETAILING REQUIREMENTS FOR HIGH-DUCTILITY RC WALLS (1998 AND 2007 CODES)

- Confined boundary elements: 0.2% reinforcement ratio (based on the total wall length) - for the plastic hinge zone (**less than CSA A23.3**)
- Min length of boundary elements = 0.2 x wall length (plastic hinge zone)
- Cross-ties prescribed to connect the reinforcement curtains
- 135-degree hooks for the ties in boundary elements;
- 90- and 135-degree hooks for the cross-ties (same as columns);




CAUSES OF DAMAGE - REINFORCED CONCRETE (RC) RESIDENTIAL BUILDINGS

Credit: SUZI-SAE



1. **Extremely high intensity of earthquake shaking (e.g. Antakya)**
2. **Deficiencies of the Seismic Force Resisting System (SFRS) for buildings with RC frames and shear walls**
3. **Configuration irregularities**
4. **Inadequate detailing of reinforcement in RC walls, columns, beams**
5. **Substandard quality of materials and construction**



2. DEFICIENCY OF THE SEISMIC FORCE RESISTING SYSTEM (SFRS): EXCESSIVE FLEXIBILITY

Three types of SFRS for RC structures permitted by the 2007 Turkish code (3.2.1.1):


- 1) **Moment frame system**
- 2) **Wall system**
- 3) **Dual frame-wall system**

Wall system has been clearly defined by the code: the walls must contribute more than 75 % to the seismic base shear force – the remaining contribution (up to 25%) by the frame.

However, the minimum required contribution of the walls in a Dual frame-wall system has not been well defined – this is a code deficiency...

Excessive flexibility of the SFRS in taller RC buildings is mostly due to inadequate amount of shear walls!


EXCESSIVE MOMENT FRAME FLEXIBILITY - AN EXAMPLE OF A BUILDING COMPLEX IN KAHRAMANMARAŞ



EXCESSIVE MOMENT FRAME FLEXIBILITY - COLUMN LAYOUT




- Majority of the columns were aligned in the N-S direction
- Very few columns aligned in E-W direction
- **Column layout inadequate for resisting lateral seismic forces in both directions**



EXCESSIVE MOMENT FRAME FLEXIBILITY - INADEQUATE SHEAR WALLS


- Many tall RC buildings with moment frames have only a few shear walls.
- In some buildings, an elevator core is the only vertical element that acts like a shear wall.
- Typical columns have an oblique (rectangular) shape, with 25 cm width and depth ranging from 60-100 cm.
- When present, shear walls are relatively short (length less than 2 meters).
- **Min required length/thickness ratio for RC shear walls = 7.0 (2007 code).**



STRUCTURAL DAMAGE (1/2)


- Some of these buildings experienced structural damage due to inadequate lateral load-resisting capacity (as expected due to inadequate amount of walls)
- In many cases the extent of structural damage was minor to moderate
- Main structural elements: columns, beams, walls (e.g. elevator core)

Elevator core damage




STRUCTURAL DAMAGE (2/2)

- It is true that columns and beams were subjected to high seismic demand, but in many cases detailing of reinforcement was deficient
- **Cross-ties missing from the constructed columns (although prescribed by the designers)!**



Column damage




NON-STRUCTURAL DAMAGE (1/2)

Interior partition walls - higher floor levels

- Extensive non-structural damage observed - particularly in masonry infills and partitions
- Damage observed both in exterior and interior infills/partitions
- Non-structural damage can be attributed to significant lateral displacements (drift) - due to excessive flexibility



Exterior infills (interior view)



NON-STRUCTURAL DAMAGE (2/2)


- Another cause of damage for nonstructural elements – poor quality of masonry materials used for infill construction
- Hollow concrete blocks – made of low-strength material, known as bimsblock or briket in Turkish – similar to AAC blocks in North America (Aerated Autoclaved Blocks)
- Wall thickness ranges from 100 to 190mm

Compressive strength – only 1.7 MPa!




BUILDING IRREGULARITIES

- Several surveyed buildings had an irregular configuration
- Common irregularities:
 - 1) Weak storey
 - 2) Vertical geometric irregularity
 - Buildings with podiums
 - Buildings with overhangs



Type 6: Discontinuity in Capacity - Weak Storey




Type 3: Vertical Geometric Irregularity

Irregularity types according to the National Building Code of Canada



WEAK STOREY (AKA "SOFT STOREY")

Many buildings in urban areas have mixed function, with the bottom floor intended for commercial use - leading to a "Soft storey" collapse mechanism




Credit: SUZI-SAE

VERTICAL IRREGULARITY: PODIUM



VERTICAL IRREGULARITY: OVERHANGS



5.

Performance of schools and Impact of earthquakes on education sector

Bishnu Pandey, PhD. P.Eng. Faculty, BCIT

Allison Chen, P.Eng., P.E, Practice Advisor , Engineers and Geoscientists BC

Turkey Earthquake

Impact on the education sector



Nearly three in every 10 earthquake-affected households assessed across Türkiye reported having no access to education

(Source : save the children report)

Key facts

- 1842 facilities completely damaged
- 637 partially damaged
- 17951 with minor damage

(source : World Bank)

As of September 2023, 27% of affected households missing education of their children

Turkey Earthquake

Observations

- Schools buildings fair better than residential buildings with minor or no damage (code enforcement)
- Most are frame structures with some shear walls incorporated
- Damages are mostly limited to non-structures and roof
- Some schools use gym for immediate shelter purpose to community
- Return rate of students was still low (by the time we visited)



Performance of Schools - Case Study


1. Nurdagi



Before




After




Performance of Schools - Case Study

2. Hatay (Hassa)

Residential homes in village




Community school



Performance of Schools - Case Study

3. Kirikhan (Kindergarten)



Fall of ceiling in the main lobby of kindergarten

Performance of Schools - Case Study

4. Hatay Kirikhan (Technical Institute)




Damage to
Roof truss



Significant
non-structural
damage in lab

Performance of Schools - Case Study

5. Bache (Osmaniye)



No significant damage



Gym used for temporary shelter

Lessons on

Performance of schools and impact on education sector

- Robust design and construction of school buildings pay off
 - Provision of shear walls
- Non-structural damages render the school unusable
- Use of Gym block as a temporary shelter (post-EQ use)
- Even minor damage in school put children off the school
- Provision of cross school admission in the disaster plan



Drawing Parallels

Prioritizing performance of school buildings in Türkiye and BC

| Türkiye | British Columbia |
|---|--|
| School buildings are “Building Use Class 1” (1.5 factor) | School buildings are “high importance” in BC Building Code (1.15 – 1.3 factor) |
| Policy to do pre-earthquake inspections of critical infrastructure and prioritization for strengthening (after 1999 Izmit EQ) | Ministry of Education’s Seismic Mitigation Program (started in 2004) |
| Guidelines for Seismic Retrofitting of School and Hospital Facilities in Istanbul | Seismic Retrofit Guidelines for Low-Rise School Buildings |
| One of first priorities for post disaster building assessments – closed for 2 weeks | |

What are the Seismic Retrofit Guidelines?


- Guidelines for the assessment and retrofit of existing low-rise school buildings in BC
- Starting in 2004, developed for the Ministry of Education by Engineers and Geoscientists BC and the University of British Columbia Civil Engineering Department
- 14 volumes with over 2000 pages
- Seismic Performance Analyzer (Analyzer I Version 4.0)



Two Underlying Goals for the Seismic Retrofit Guidelines

1. Implement seismic retrofits that achieve a life safety objective in a cost-effective manner
2. To adopt a common engineering approach to the seismic retrofit of school buildings

Underlying goal of the Ministry of Education to mitigate the risk of seismically deficient buildings in their inventory.





Liquefaction

Key Components in the SRG that Address Issues Experienced in Turkiye

Operational & Functional Components



Post-Earthquake Evaluation Guidelines


Table 2.1: Description of Four PSR Categories for Rating H1 High Risk Blocks for Moderate Level of Shaking

| PSR Category | PSR Rating | PSR Category Description |
|--------------|------------|---|
| P1 | #1 | (a) Total damage (b) Highest life safety consequences (c) Demolition post-event outcome |
| P2 | #2 | (a) High probability of total damage (b) High life safety consequences (c) Demolition probable post-event outcome |
| P3 | #3 | (a) Moderate probability of total damage (b) Moderate life safety consequences (c) High post-event repair costs |
| P4 | #4 | (a) Low probability of total damage (b) Low life safety consequences (c) Readily repairable post-event |


Seismic Mitigation Program Summary (September 2023)

| | |
|------------|----------------------------|
| 219 | Schools Completed |
| 12 | Under Construction |
| 5 | Proceeding to Construction |
| 17 | Business Case Development |
| 244 | Future Priorities |
| 497 | TOTAL PROJECTS |


Non-ductile Concrete Frame



URM with Ineffective Roof




URM with Effective Roof




Clay Brick with Concrete Diaphragms




Clay Brick with Ineffective Roof




One Storey 1950s Wood Frame



Two Storey 1950s Wood Frame



Wood Frame with Basement Pony Walls



Gym – Wood Frame



Final Words – Application to Low-Rise Buildings

SRG 2020 Training Workshop, May 5, 2023:

For seismic retrofits of existing buildings from “voluntary upgrades” through to “major renovations” the SRG is one methodology, that has been internationally peer reviewed, for achieving the acceptable alternative solutions identified in the Design Upgrade Level Tables provided in the revised Vancouver Building Bylaw



6. Performance of Health Care Facilities

Jeffrey Salmon, Ph.D., Structural EIT, Ausenco Engineering Canada Ltd.



Base Isolation Legislation for Health Care Facilities in Türkiye

- Turkish Ministry of Health issue a law in 2013:
 - “Hospital Buildings, located in seismic zones 1 and 2 with number of bed capacity over 100 should be constructed with base-isolation.”
 - In 2017, a code on Seismic Isolation Design for Building Structures was prepared and enforced in January of 2019
- As of 2017, there were 72 base-isolated structures (e.g., hospitals, schools, airport terminals) in Türkiye


Reference:

Erdik, Mustafa, et al. "Seismic isolation code developments and significant applications in Turkey." *Soil Dynamics and Earthquake Engineering* 115 (2018): 413-437.


Base Isolated and Conventional Structure



Friction Pendulum Isolators




12 Hospitals Visited in the Earthquake Affected Areas



Reference:

Qu, Zhe, et al. "Rapid report of seismic damage to hospitals in the 2023 Turkey earthquake sequences." Earthquake Research Advances (2023)




Base-Isolated Hospital: Malatya



Reference:

Qu, Zhe, et al. "Rapid report of seismic damage to hospitals in the 2023 Turkey earthquake sequences." Earthquake Research Advances (2023)

Fixed-Base Hospital: Malatya



Reference:

Qu, Zhe, et al. "Rapid report of seismic damage to hospitals in the 2023 Turkey earthquake sequences." Earthquake Research Advances (2023)

Fixed-Base Hospital: Nurdagi

- Nurdagi population of 41,000
- Built in 2003, upgraded in 2015
- Hospital was out of service; significant non-structural damage.



Google Maps – May 2021



June 5, 2023

Fixed-Base Hospital: Nurdagi



Fixed-Base Hospital: Nurdagi



Fixed-Base Hospital: Islahiye

- Islahiye population of 67,650
- Hospital is located roughly 100 m from the fault line
- Hospital remained operational after the earthquake




Google Maps – November 2022



June 5, 2023

Fixed-Base Hospital: Islahiye



Reference:

Dr. Ramazan Demirtaş [@Paleosismolog]. Images of Islahiye hospital. X. February 26, 2023. <https://twitter.com/Paleosismolog/status/1633621597977210880>

Base-Isolated Hospital: Malatya

- Malatya population of 797,000
- 200-bed hospital
- Hospital was operational during and after the EQ

Base Isolated Hospital

Hospital built in the 1930s.



Base-Isolated Hospital: Malatya



Base-Isolated Hospital: Malatya

Hospital has 5 back-up generators and additional purifying systems



Base-Isolated Hospital: Malatya

Pumice-like material was used in the moat (crushable material)



Base-Isolated Hospital: Osmaniye

- Osmaniye population of 534,000
- Base-Isolated hospital
- 600-bed hospital
- Hospital under construction during the earthquakes; started operation after the EQ



Base-Isolated Hospital: Osmaniye




Base-Isolated Hospital: Osmaniye



Base-Isolated Hospital: Osmaniye

Flexible connections between at the interface between the isolated and superstructure and fixed substructure



General Observations

- The hospitals were subjected to significant ground shaking during the earthquakes
- Base isolated hospitals performed well and continued operation during and after the earthquakes
 - One base-isolated hospital suffered nonstructural damages and was closed – this was a result of filling the moat, which hindered the performance of the isolators
- Nonstructural damage in fixed-base hospitals resulted in their closure
 - Structural damage resulted in the closure of hospitals built before 2001

7. Preparedness, Response, and Recovery

Allison Chen, P.Eng., P.E., Practice Advisor, Engineers and Geoscientists BC
Şerife ÖZATA, Ph.D., Architect, Research Assistant, Kirsehir Ahi Evran University
Jeffrey Salmon, Ph.D., Structural EIT, Ausenco Engineering Canada Ltd.




Response and Recovery Timeline (First 2 Months)




Response and Recovery

Tents and Shelter Areas



Response and Recovery

Containers and Shelter Areas



Response and Recovery - Containers and Earthquake Housing



Hatay Qatar Funded Container City

Hatay



Earthquake Housing Const., Sept.'23



Osmaniye

Kilis



Container City



Earthquake Housing Const., June.'23



Container City

Sanliurfa



Earthquake Housing Const., June'23



Gaziantep

Container Area



Earthquake Housing Const., Sept.'23

Response and Recovery

Containers and Earthquake Housing



Kahramanmaraş

Eq. Housing Const., July. '23



Earthquake Housing Const., July. '23



Adiyaman K-2B Container City
Adiyaman



Earthquake Housing Const., Aug. '23



Kahramanmaraş Elbistan Container City



Malatya

Malatya Dogansehir Container City, April '23



Diyarbakir Kayapinar Container City

Earthquake Housing Const., Sept '23

Diyarbakir



Adana

Eq. Housing Const., Aug. '23



Adana Şambayadı
Temporary Shelter Area



Response and Recovery

Debris clean-up started on a large-scale February 23, 2023

- Material separated to be recycled



Reported Issues of the Response and Recovery

- Damaged airport runway in Hatay delayed rescue efforts; airport was reopened 6 days after the earthquakes.
- Rescue and aid delayed in some regions due to inaccessibility
- Mismanaged distribution of goods reported in some areas
- In some areas, water, sanitation and hygiene conditions need improvement

Damage Assessment



Response and Recovery

Damage Assessment

Post-earthquake damage assessment is the process of **observationally evaluating** and **classifying the damage** caused by the earthquake to the building by a technical team.

The assessment

- does **not consider the potential damage** that a larger earthquake in the region could cause
- is not the determination of whether the **building is earthquake resistant or not**.

The assessment methodology → **rapidly applicable** and **straight forward**
number of buildings requiring inspection and the shortage of qualified inspectors

The Damage Assessment Methodology has been developed by **Prof. Dr. Alper İlki and his team (2021)**.
It has been used in many earthquakes to evaluate the damages in reinforced concrete (RC) and masonry structures.
+several adjustments and improvements to enhance its applicability.

It is accepted by Ministry of Environment, Urbanization and Climate Change (MoEUCC) as a general damage assessment method in crisis situations.



[1] İlki, A., O. F. Halici, M. Comert, and C. Demir. 2021. The modified post-earthquake damage assessment methodology for TCIP (TCIP-DAM-2020). In Advances in assessment and modeling of earthquake loss, ed. S. Akkar, A. İlki, M. Erdik, and C. Goksu, 85–107. Cham: Springer.

Damage Assessment System

Building Damage Categories

Undamaged Building

No earthquake damage



Dulkadiroğulları, Kahramanmaraş

Slightly Damaged Building

Minor damages



Bahçe, Osmaniye

Moderately Damaged Building

Certain decrease in the capacity



Nurdagi, Gaziantep

Heavily Damaged Building

Significant lost of pre-earthquake performance



Nurdagi, Gaziantep

Building to be Urgently Demolished

partial collapse, residual displacements



Kırıkhan, Hatay

Collapsed Building

Complete collapse






Kömürler, Gaziantep

Damage Assessment System

Damage Categories for RC Members



| Damage Category | Residual crack width (w) | Compression damage |
|-----------------|--------------------------------|--|
| Type 0 | - | - |
| Type A | $w \leq 0.5 \text{ mm}$ | - |
| Type B | $0.5 \leq w \leq 3 \text{ mm}$ | Cover crushing |
| Type C | $> 3 \text{ mm}$ | Cover spalling |
| Type D | - | Buckling of reinforcement, core crushing residual displacement |



Damage Assessment System

Damage Assessment Algorithm

This algorithm consists of a two-stage procedure;
Exterior assessment and Interior assessment.



Damage Assessment System

Exterior Assessment

1. Is there total collapse?

Yes →

Collapsed Building



No ↓

2. Is there partial collapse?

Yes →

Building to be Urgently Demolished




No ↓
Continue...

Damage Assessment System

Exterior Assessment


3. Is there any permanent horizontal residual displacement measured at any story in the building is greater than 1% of the corresponding story height?



$$d/h > 0.01$$

No

4. Does the structure experience a rigid rotation exceeding 2° due to earthquake-induced settlements?



No

Interior assessment

Yes

>1%

Heavily Damaged Building

>3%

Building to be Urgently Demolished

Yes

>2°

Heavily Damaged Building

>4°

Building to be Urgently Demolished

Damage Assessment System

Interior Assessment


Three levels of interior inspection are possible depending on the *urgency of the inspection, extent of damage in the city and size of the building*:

- Detailed Assessment,
- Rapid Assessment,
- **Assessment in Crisis Situations.**

It is applicable for ;

- Low and mid-rise buildings ≤ 10 stories
- Plan area $\leq 800 \text{ m}^2$

*Initiate the assessment from the most damaged floor of the building.



Damage Assessment System

Interior Assessment

1. Is the number of columns or shear walls that have Type D damage equal to or bigger than 1?

Yes, ≥ 1

Heavily Damaged Building



Heavily Damaged Building

Yes, ≥ 2

No

2. Are there any Type C damaged columns or shear walls in the structure, and if so, how many?

No

Continue...




| Damage Category | Residual crack width (w) | Compression damage |
|-----------------|--------------------------------|---|
| Type 0 | - | - |
| Type A | $w \leq 0.5 \text{ mm}$ | - |
| Type B | $0.5 \leq w \leq 3 \text{ mm}$ | Cover crushing |
| Type C | $> 3 \text{ mm}$ | Cover spalling |
| Type D | - | Buckling of reinforcement, core crushing, residual displacement |


Damage Assessment System

Interior Assessment

3. Is the number of damaged elements of **Type B** < 3 if no damaged elements of **Type C** or **D** are observed?

| Damage Category | Residual crack width (w) | Compression damage |
|-----------------|--------------------------------|---|
| Type 0 | - | - |
| Type A | $w \leq 0.5 \text{ mm}$ | - |
| Type B | $0.5 \leq w \leq 3 \text{ mm}$ | Cover crushing |
| Type C | $> 3 \text{ mm}$ | Cover spalling |
| Type D | - | Buckling of reinforcement, core crushing residual displacement |


Yes, < 3 

No, ≥ 3 

Slightly
Damaged
Building


Moderately
Damaged
Building

4. Are all damages **Type A**, regardless of the number?

Yes 

Slightly
Damaged
Building

If there is not any earthquake-induced damage

Yes 

Undamaged
Building

Damage Assessment System

- quickly implementable
- easy to follow
- **easy to understand**

Printed damage assessment sheet

| | |
|----------------------------------|--|
| Investigation date: | |
| Team members: | |
| Building code: | |
| Address: | |
| Building construction date: | |
| Structural system type: | *Reinforced concrete *Masonry *Other(.....) |
| Floor: |Basement+Ground+Suspended floor(exist/not)+floor+roof floor(exist/not) |
| Plan area: | m ² |
| Building type (purpose of usage) | |

Exterior assessment

1. Is there any total or partial collapse? yes no

2. Is there any permanent horizontal residual displacement measured at any story in the building is greater than 1% of the corresponding story height? yes no

3. Does the structure experience a rigid rotation exceeding 2° due to earthquake-induced settlements? yes no

**If yes to any of the questions above, the building is heavily damaged. Note the buildings that need to be demolished urgently.*

**If all answers are no, proceed to interior assessment.*

Interior assessment (Initiate the assessment from the most damaged floor of the building.)

4. Is the number of **Type D** damaged columns or shear walls ≥ 1 ? yes no

5. Is the number of **Type C** damaged columns or shear walls in the structure ≥ 2 ? yes no

**If any of questions 4 and 5 are yes, the building is heavily damaged.*

6. None of the columns and shear walls are damaged **Type C** or **D**, but the number of elements damaged **Type B** is <3 ? yes no

**If the answer to question 6 is "yes", the building is "slightly damaged", if the answer to question 6 is "no", the building is "moderately damaged".*

Final Damage Assessment: Undamaged Slightly damaged Moderately Damaged
 Heavily Damaged To be demolished urgently Collapsed

Notes:

Bina Bilgileri Formu

Bina Adres Bilgileri - UAVT

Şehir: Gaziantep

İlçe: Şirvanlı

Bucak: ...

Köy: ...

Mahalle: ...

Cadde/Sokak/Bina/Meydan: ...

Bina: ...

Bina Kategorisi (*)

Katmanlı Bilinici (Y)

Brüt Taban Alanı(m²) (*): 330

Brüt Toplam Alanı(m²) (*): 1320

Kullanıcı Notu: Bina tretuvarlarında çatlak var.

BINA YIKILDI

Bina, karşılıklı çarpaz iki köşeden fotoğraflanacak (*)

Number of Buildings Included in Damage Assessment (6 March 2023)

| Status | Number of Buildings | Number of Detached Units |
|-----------------------------|---------------------|--------------------------|
| Undamaged | 860,006 | 2,387,163 |
| Lightly Damaged | 431,421 | 1,615,817 |
| Moderately Damaged | 40,228 | 166,132 |
| Severely Damaged | 179,786 | 494,588 |
| Collapsed | 35,355 | 96,100 |
| Requiring Urgent Demolition | 17,491 | 60,728 |
| Not Assessed | 147,895 | 296,508 |
| Total | 1,712,182 | 5,117,036 |

Source: MoEUCC

<https://www.sbb.gov.tr/wp-content/uploads/2023/03/2023-Kahramanmaras-and-Hatay-Earthquakes-Report.pdf>

Ongoing Recovery and Societal Impact

- Community
- Home Life
- School life
- Work Life



Community

Municipalities and NGOs providing ongoing social services

- Meals
- Psychosocial support
- Free public transportation

Continuing redevelopment

- Prefabricated single family dwellings
- Tunnel form multi-storey, multi-unit buildings



Home Life

- Tent cities continue to be replaced with container cities
- Residents returning to lightly damaged buildings

Long term recovery is long term.

- First rebuilt residences expected to be completed in January 2024
- Full recovery expected to be 3-5 years for worst-hit areas



School Life

- Priority to get children back to school as quickly as possible
- Schools with light damage were used as shelters
- Schools continue to be used to store food and donated goods
- Tents and temporary buildings




Work Life

- Business as usual as best as possible
- Container and temporary structures allocated for bazaars and markets - lottery system for tenancy
- Prefabricated commercial buildings under construction



Earthquake Preparedness

- Overview
- Institutional Setup & Responsibilities
- Turkiye Disaster Response Plan (TARP)
- Turkiye Disaster Risk Reduction Plan (TARAP)
- Examples of Earthquake Preparedness
- BC Resources



References:

- Kahramanmaraş and Hatay Earthquakes Report (Gov. Turkiye, 2023)
- British Columbia Emergency Management System Guide (Gov. BC, 2016)
- An Emergency Management Framework for Canada (Gov. Can., 2016)

Institutional Setup & Responsibilities

Disaster and Emergency Management Agency (AFAD)


- Develop Turkiye Disaster Risk Reduction Plan (TARAP)
- Develop Turkiye Disaster Response Plan (TAMP)
- Execution of disaster response process

Ministry of Environment, Urbanization and Climate Change (MoEUCC)

- Activities related to spatial planning, geological surveys and geographic information systems
- Damage assessment studies
- Demolition of damaged buildings
- Debris removal

Türkiye Disaster Risk Reduction Plan (TARAP)

- Follows the Sendai Framework (2015-2030)
- Identifies objectives, goals, and actions for disaster risk reduction
- For earthquakes it includes:
 - 7 objectives (out of 66)
 - 29 actions (out of 227)
- Key actions include:
 - Determining Türkiye's crustal structure and model
 - Monitoring crustal deformations in active fault zones,
 - Preparing liquefaction potential maps and local scale soil amplification potential maps



Develop Türkiye Disaster Response Plan (TAMP)

Prepared in 2004, updated in 2022 to:

- Ensure effective response to disasters (11 kinds)
- Minimize operational risks during disasters

Does this by:

- Determining the basic principles of response planning before, during, and after disasters
- Identifying the roles and responsibilities of the working groups and coordination units (28 total)

Requirements for success:

- All responsible groups own it
- Organizations coordinate with each other
- Actions are performed on time and in accordance with the general principles of the plan

Mitigation

- Codes - updated based on research and past earthquakes
- Hospitals - require base isolation
- Schools & Hospitals - designed as high importance, seismic upgrades



Preparedness

- Development of Turkiye Disaster Response Plan
- Development of Turkiye Disaster Risk Reduction Plan
- Training on post disaster building assessments
- Earthquake drills for students (4/year)



Response

- Humanitarian aid – Turkish Red Crescent, Ministry of National Defense
- Execution and coordination of response efforts
 - Post disaster building assessments, demolition, debris removal, etc.



Recovery

- Determine which buildings will be retrofitted or demolished and rebuilt
- Determine how and where to rebuild
- Project management for housing developments



(a few) Key Takeaways for Türkiye and British Columbia

Make good development and land use planning decisions

Prioritize social support for communities

Educate engineers, contractors, and municipalities about seismic design and construction

Increase quality control of materials and processes

Ensure infrastructure can withstand and perform after the earthquake so people and resources can move in and out

Train locals to respond and participate in search and rescue, first aid, post disaster building assessments, etc.

Designate sister province(s) for each, considering geographical distance, population size, and disaster risks

Conduct risk analyses and post-earthquake predictions to inform response and/or retrofit priorities

8.

Concluding remarks

Tony T.Y. Yang, Ph.D., P.Eng., F.CAE, Professor, UBC



Acknowledgement:

UBC APSC

SEABC
program

certificate

CAE



THE UNIVERSITY OF BRITISH COLUMBIA

Engineering

Faculty of Applied Science



All local contacts (in alphabetical) in Türkiye:

Ali Gemci, Director of Urban Planning of Onikişubat Municipality; Ali Gül, Headman of Hacilar Village; Ali Osman Coşkun, Hüseyin Sünnetçioğlu, Abdulmutalip Barubay, Sedat Humartekin in BRY and GNR Altyapı Inc.; Alpay Atmaca, Engineer in Osmaniye State Hospital; Bülent Haksal, Director of Disaster Coordination of Gaziantep Municipality in Nurdağ; Eflahun Yıkıcı, Guard in Kartalkaya Dam in Pazarcık; Engin Özer, The deputy mayor of Antakya Municipality; Enver Kaya, Controller in the Kartalkaya Dam; Erdoğan Emrah Hatunoğlu, Director of Foreign Relations of Kahramanmaraş Municipality; Halil Satıcı, Manager of Social Affairs of Gaziantep Municipality in Nurdağ; Hasan Ay, District Director of National Education in Kırıkhan; H. Abdullah Dinç, Head of Industrial Vocational High School in Kırıkhan; İbrahim Hızıyolu, Director of Disaster Coordination of Gaziantep Municipality in Islahiye; Kemal Topçu, Head of 75. Yıl Kindergarten in Kırıkhan; M. Fatih Tosyalı, Mayor of İskenderun Municipality; Metin Çiftçi, Site Manager of the Tunnel and Bridge in Gölbaşı; Muharrem S. Bilgiç, Project Coordinator in Intek Inc. in Islahiye; Mürsel Koçer, Head of Osmaniye State Hospital; Rüstem Keleş, General Secretary of Kahramanmaraş Municipality; Sait Bayraktar, District Director of National Education in Hassa; Osman Tuğrul Adıgüzel, Head of Bahçe High School in Bahçe; Özgür İspir, Representative of Chamber of Civil Engineering in Elbistan; Uğur Pekmez, Pekmez Inc. in Kahramanmaraş; Uğur Yücel, Architect in Gölbaşı; Yusuf Dedeoğlu, Head of Hacılar Middle School in Hassa



THE UNIVERSITY OF BRITISH COLUMBIA

Engineering

Team:



Tony T.Y. Yang
Professor
UBC



Carlos Ventura
Professor
UBC



Alemdar Bayraktar
Visiting Professor
UBC



Svetlana Brzev
Adjunct Professor
UBC



Mehrtash Motamedi
Research Associate
UBC



Bishnu Pandey
Instructor
BCIT



Allison Chen
Practice Advisor
EGBC




Jeffrey Salmon
Structural Engineer
Ausenco Eng. Canada



Keshab Sharma
Geotechnical Engineer
BGC Engineering



Şerife Özata,
Architect
AEU, Kirsehir




Omar AlShawa
Research Associate
SUR



Veljko Kokovic
Assistant Professor
U of Belgrade





- Day 1
- Day 2
- Day 3
- Day 4
- Day 5



Gaziantep

Aleppo

Lake Assad

Niğde

Adana

Mersin

İskenderun

Aleppo

Kahramanmaraş

Adiyaman

Sanliurfa

Gaziantep

Aleppo

Lake Assad

Niğde

Adana

Mersin

İskenderun

Aleppo

Kahramanmaraş

Adiyaman

Sanliurfa

Gaziantep

Aleppo

Lake Assad

Visited the disaster sites:



Structural examination:



Examine the foundation failure sites:



Reconstruction sites:



- The newly constructed village. 400 units, each 1280 sf (3 rooms, 1 living room and a kitchen).
- Cost of one house is ~100,000 USD, and each family will pay 40,000 USD (24 years mortgage) with the remaining amount covered by the government.
- Cold-formed steel fabricated.
- Each house is completed in 20 days with 50 workers.
- Began on March 10, 2023, and it is planned to be completed in 9 months.



Visited the dam:



On-site measurement:



Visited to health care facilities:




Interacted with government officials:



Interacted with government officials:



Interviewed by the local media:



Turkish Press News

<https://www.habertime.com.tr/kanadali-bilim-insanlari-deprem-bolgesini-inceledi>

<https://www.iha.com.tr/kahramanmaras-haberleri/-4380511>

<https://www.turkiyegazetesi.com.tr/teknoloji/kanadali-bilim-insanlari-felaketin-boyutunu-ve-izlerini-inceledi-970598>

<https://kinikgazetesi.com/kanada-british-columbia-universitesi-heyetinden-osmaniye-ziyareti/>

<https://www.elbistaninsesi.com/haber/15303610/kanadali-bilim-insanlari-felaketin-boyutunu-ve-izlerini-inceledi>

<https://www.egegundem.com.tr/video/15340034/felaketin-boyutlarina-inanamadilar>

<https://www.memleket.com.tr/kanadali-bilim-insanlari-felaketin-boyutunu-ve-izlerini-inceledi-2244821h.htm>

<https://beyazgazete.com/haber/2023/6/12/kanadali-bilim-insanlari-felaketin-boyutunu-ve-izlerini-inceledi-6815912.html>

https://www.tucsa.org/tr/haber_detay.aspx?haber=4391

<https://kahramanmaras.bel.tr/haber/2023/06/09/uluslararasi-akademisyenlerle-afet-yonetimi-toplantisi-yapildi>

Connected with the locals:



Having great time:



| Time | Title of Presentations | Speaker(s) | Affiliation |
|----------------|---|---|--|
| 1:00 – 1:05 pm | Opening Remarks from Consul General of Türkiye | Mr. Hüseyin Emrah Kurt | Consul General of Türkiye |
| 1:05 – 1:20 pm | Introduction | Tony Yang | Professor, UBC |
| 1:20 – 1:40 pm | Seismology and Geotechnical Effects | Alemdar Bayraktar Keshab Sharma Carlos E. Ventura | Visiting Professor, UBC (Remote) Geotechnical Engineer, BGC Engineering Inc. (Remote) Professor, UBC |
| 1:40 – 2:00 pm | Building Codes and Construction Practices | Tony Yang | Professor, UBC |
| 2:00 – 2:20 pm | Break | | |
| 2:20 – 2:40 pm | Performance of Residential Buildings | Svetlana Brzev | Adjunct Professor, UBC |
| 2:40 – 3:00 pm | Performance of Schools Buildings | Bishnu Pandey Allison Chen | Instructor, BCIT Practice Advisor, EGBC |
| 3:00 – 3:20 pm | Performance of Health Care Facilities | Jeffrey Salmon | Structural Engineer, Ausenco |
| 3:20 – 3:40 pm | Break | | |
| 3:40 – 4:20 pm | Preparedness, Response, and Recovery | Allison Chen Jeffrey Salmon Serife Ozata | Practice Advisor, EGBC Structural Engineer, Ausenco Research, teaching assistant, Ahi Evran University (Remote) |
| 4:20 – 4:50 pm | Panel Discussion | All | |
| 4:50 – 5:00 pm | Concluding Remarks | Tony Yang | Professor, UBC |

Some of the takeaways

Social and economic effects:

- 11 major city centres and 14 million people were affected, and north part of Syria.
- A total of 50,783 people lost their lives, and 115,353 people were injured.
- The number of collapsed or urgently demolished buildings in the region is reported as 58,039, while the number of severely damaged buildings is 205,534 (May 2, 2023).
- Housing sector: 56.9 billion USD
- Deconstruction sector: 12.9 billion USD
- Private industries (including manufacturing, energy, communications, tourism, healthcare, education sectors): 11.8 billion USD
- Other insurance section
- Total economy loss: 103.6 billion USD (~9% of GDP of Türkiye in 2023)

Some of the takeaways

Seismology and geotechnical effects:

- Recorded PGA, PGV, PGD and spectral values significantly exceeded the design values in many locations.
- Back-to-back effects of the earthquake sequencies on structures.
- Effects of near-fault, basin and soil amplification.
- Effects of shallow earthquake (less than 10km deep).
- Effects of long duration of the ground shaking.
- Proximity of epicenters and fault lines to urban centers.
- Effects of long ruptured fault system.
- Widespread liquefaction on wetlands and along the costal line

Some of the takeaways

Turkish Building codes:

- Turkey has a long history of earthquakes
- Turkish building code has been significantly modified over the years to account for the earthquake effects
- The most current Turkish building code has accounted for many of the state of the art practice and research
- Turkey is proactive in using seismic protective technology, such as base isolation. Over 72 major Turkish infrastructures have been protected using base isolation systems.

Some of the takeaways

Performance of Residential Buildings:

- **Predominantly constructed using cast-in-situ reinforced concrete (RC) technology.**
- **Older mid-rise RC buildings constructed before 2000 did not perform well due to absence of ductile design and detailing; soft storey collapse was common in the buildings with an open ground floor.**
- **Majority of post-2000 RC buildings (designed according to modern seismic codes) did not collapse, except for the buildings with major design and/or construction deficiencies.**
- **Majority of the buildings (including those with only minor structural damage) experienced extensive non-structural damage and/or collapse of masonry infills and partitions.**
- **Many buildings had to be vacated due to extensive non-structural damage and are likely going to be replaced - even though the structural system may be repairable.**

Some of the takeaways

Performance of School Buildings:

- Robust design and construction of school buildings pay off
- Non-structural damages render the school unusable and hence need special attention
- Use of Gym block as a temporary shelter (post-EQ use) helps towards effective immediate response.
- Need to start school for higher importance
- Need special guidelines targeting schools
- Need to ensure the school can have higher performance where it can functional after the earthquake

Some of the takeaways

Performance of health care facilities:

- Base isolated hospitals performed well and continued to be operation during and after the earthquakes
- One base-isolated hospital suffered nonstructural damages and was closed – this was a result of filling the moat, which hindered the performance of the isolators
- Nonstructural damage in fixed-base hospitals resulted in their closure
 - Structural damage resulted in the closure of hospitals built before 2001

Some of the takeaways

Preparedness, Response, and Recovery:

- Turkey has done well in the preparedness, response and recovery.
- They have made good development and land use planning decision
- Prioritizes social support for communities
- Educate engineers, contractors, and municipalities about seismic design and construction
- We need to start planning to ensure infrastructure can withstand and perform after the earthquake so people and resources can move in and out
- We shall start designing our neighboring, cities, province(s) to work together to withstand the earthquake impact
- Conduct risk analyses and post-earthquake predictions to inform response and/or retrofit priorities.

Thank you

